




FARGO® HDP®5000 LAMINATOR FIRMWARE RELEASE NOTES

Release: 1.3.2

PLT-04851, Rev. A.0

January 2020



Copyright

© 2020 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, FARGO and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Revision history

Date	Description	Revision
January 2020	Initial release.	A.0

Contacts

For additional offices around the world, see www.hidglobal.com/contact/corporate-offices.

Americas and Corporate	Asia Pacific
611 Center Ridge Drive Austin, TX 78753 USA Phone: +1 866 607 7339 Fax: +1 949 732 2120	19/F 625 King's Road North Point, Island East Hong Kong Phone: +852 3160 9833 Fax: +852 3160 4809
Europe, Middle East and Africa (EMEA)	Brazil
Haverhill Business Park, Phoenix Road Haverhill, Suffolk, CB9 7AE United Kingdom Phone: +44 (0) 1440 711 822 Fax: +44 (0) 1440 714 840	Condomínio Business Center Av. Ermano Marchetti, 1435 Galpão A2 - CEP 05038-001 Lapa - São Paulo / SP Brazil Phone: +55 11 5514-7100

HID Global Technical Support: www.hidglobal.com/support.

1 Scope

These release notes provide information on the FARGO® HDP®5000 Laminator Firmware version 1.3.2. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from a HID Global internal tracking system.

2 Resolved Issues

- Resolved an issue where dual sided laminators would occasionally fail to put the lamination head modules into proper position for lamination and may prematurely lift causing Error 217 or Error 218 or fail to complete the lamination of the full card leaving patches with incomplete adhesion. (Reference No. QA6724).

Note: After updating the firmware to version 1.3.2, the following options must be adjusted within the **Printing Preferences > Card > Toolbox > Advanced Settings** tab:

Option	Action required
Lamination Top Takeup	Set to 0
Lamination Bottom Takeup	Set to 0
Lamination Top of Form	Adjust as required to ensure correct lamination placement
Lamination End of Form	Adjust as required to ensure correct lamination placement

